COVERALL CLEAN & AUTOCLAVE FOR «CLEAN ROOMS»

The COVERALL CLEAN & AUTOCLAVE goggles have been especially developed to guarantee high protection & comfort in risky environments, like pharmaceutics, micro-electronics or even surgery departments.





COVACLAVE

79 a







// COVACLAVE

- + CLEAN ISOPRENE STRAP
- + OVERFLOW CHUTE FOR LIQUIDS
- + FITS OVER PRESCRIPTION SPECTACLES
- + TPR FRAME / UPPER INDIRECT VENTILATION / SEALED IN THE LOWER PART
- + HIGH-COMFORT AUTOCLAVABLE GOGGLE
- + 😵 PLATINUM' COATING (*P)

- // COVACLEAN
- + CLEAN ISOPRENE STRAP
- + OVERFLOW CHUTE FOR LIQUIDS
- + FITS OVER PRESCRIPTION SPECTACLES
- PVC FRAME / UPPER & LOWER INDIRECT VENTILATION
- + STERILISABLE BY GAMMA & BETA RADIATION



COVERALL CLEAN & AUTOCLAVE FOR «CLEAN ROOMS»

MODEL	VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
COVERALL	Ventilated	COVACLEAN	2C-1,2 🗁 1 BT C€	ʿंਟੋਂ EN166 3 4 BT C€	ASAF
COVENALE	Semi-ventilated	COVACLAVE	2C-1,2 🗁 1 FT KN CC	🗁 EN166 3 4 FT C €	Anti-scratch/Anti-fog (*P)

LENS MARKING

Optical class symbols:

1. Continuous work

Mechanical strength symbols:

- B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s.
- F. Low energy impact, resists a 6 mm, 0.86 g ball at 45 m/s.
- T. The letter T, immediately after the mechanical strength symbol,
- authorises use for high speed particles at extreme temperatures. Others symbols:
- K. Resistance to surface damage by fine particles
- N. Resistance to fogging

TECHNOLOGY

C€ European standard ☐ Manufacturer name

resistant and durably delays the appearance of fogging.

FRAME MARKING

EN 166: guaranteed minimum resistance of the protective eyewear against everyday risks including dropping the protective eyewear onto the ground, ageing by light exposure, exposure to heat or corrosion etc.

- 3. Liquid droplets or splashes.
- 4. Large dust particles > 5 microns.
- F. Low energy impact, resists a 6 mm, 0.86 g ball at 45 m/s.
- B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s.
- T. The letter T, immediately after the mechanical strength symbol, authorises use for high speed particles at extreme temperatures.
- C€ European standard ☐ Manufacturer name

Bollé Safety product approval certificates to CE standards will be sent on request.

CLEANING AND STORAGE

CLEANING: The lenses should be cleaned regularly. Bollé Safety recommends only using the B-clean lens cleaning system.

MAINTENANCE: Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: All products must be stored in a dry and clean environment.

CHARACTERISTICS			
LENSES	PC - 2,2 mm - Curve 4		
FRAME	PVC (CLEAN) / TPR (CLAVE)		
TEMPLES	Non applicable		
STRAP	Adjustable - Isoprene		
FOAM	No		
MAINTENANCE AND CLEANING	Soapy water		
STERILIZATION Covaclave	121° / 20 mn / 50 Cycles		

12/02/2019



	PACKAGING AND EAN 13 CODE					
		COVACLEAN	COVACLAVE			
-	Individual plastic bag	3660740007850	3660740000646			
	5 safety goggles per box	3660740107857	3660740100643			
	90 safety goggles per outer pack	3660740207854	3660740200640			



Europe Bollé Safety 34 rue de la soie 69100 Villeurbanne - France Tél.: 00 33 (0) 4 78 85 23 64 Fax: 00 33 (0) 4 78 85 28 56 contact@bolle-safety.com

U.K. Bollé Safety Unit C83 - Barwell Business Park Leatherhead Road - Chessington Surrey - KT9 2NY - UK Tél.: 00 44 (0)208 391 4700 Fax: 00 44 (0)208 391 4733 e-mail : sales@bolle-safety.com

bolle-safety.com

PACKAGING AND EAN 13 CODE					
	COVACLEAN	COV			
ual plastic bag	3660740007850	36607			

The new exclusive scratch and fog resistant coating PLATINUM® guarantees

even more safety, reliability and comfort. Washable (water and soap), this permanent coating applied on both sides of the lens makes it highly scratch

3660740207854	36607402